



NMAH SPACE 3204

								Material		New Sample	
ID	Status	Hazard Type	Description	Comments	Reference ID	Reference Source	Material Type	Condition	Material Location	Results	
			Drywall joint compound.				Drywall and Joint	G = Good:			
HAZ 19909	Removed	Asbestos	Throughout (4,000 SF).		Heart House	AMA 2009	Compound	material intact	Throughout (4,000 SF)		
						28-Jul-20 OSHEM/Kapranos	Textile, Theater	G = Good:			
HAZ 20782	Removed	Asbestos	Black backdrop cloth		2003106	asbestos survey	Curtain	material intact	South and west walls	July 2020	
								G = Good:	Located at the HVAC supply		
HAZ 20786	Removed	Asbestos	Blue HVAC filter.				HVAC Filter	material intact	registers		
									East side of room under		
			Crawlspace pink insulation						elevated floor. Access is a few		
			located under the elevated floor					G = Good:	feet from the starboard side		
HAZ 20784	Removed	Asbestos	in the east side of the room.				Insulation, Ceiling	material intact	of the boat.		
			Yellow HVAC duct insulation			28-Jul-20 OSHEM/Kapranos	Insulation, HVAC	G = Good:			
HAZ 20785	Removed	Asbestos	with black painted wrap.		2003106	asbestos survey	Duct	material intact	Throughout ceiling	July 2020	
			Off-white backdrop			28-Jul-20 OSHEM/Kapranos	Textile, Theater	G = Good:			
HAZ 20783	Removed	Asbestos	clothtextile/mesh		2003106	asbestos survey	Curtain	material intact	South and west walls	July 2020	

NMAH SPACE 3208

				Comment						
ID	Status	Hazard Type	Description	s	Reference ID	Reference Source	Material Type	Material Condition	Material Location	New Sample Results
						OSHEM 25Jan18 asbestos survey				
	Remove		Drywall joint compound.			report (Project 1803102),				
HAZ 19913	d	Asbestos	Throughout (1,200 SF).		Heart House	Original survey AMA 2009	Drywall and Joint Compound	G = Good: material intact	Throughout (1,200 SF)	

NMAH SPACE 3000S6

										New Sample
ID	Status	Hazard Type	Description	Comments	Reference ID	Reference Source	Material Type	Material Condition	Material Location	Results
			Drywall/joint compound painted			28-Jul-20 OSHEM/Kapranos	Drywall and Joint	G = Good: material		
HAZ 20787	Removed	Asbestos	off-white and black.		2003106	asbestos survey	Compound	intact	Throughout room.	July 2020
						28-Jul-20 OSHEM/Kapranos		G = Good: material	Located at the HVAC	
HAZ 20789	Removed	Asbestos	Blue HVAC filter.		2003106	asbestos survey	HVAC Filter	intact	supply registers	July 2020
			Yellow HVAC duct insulation			28-Jul-20 OSHEM/Kapranos	Insulation, HVAC	G = Good: material		
HAZ 20788	Removed	Asbestos	with black painted wrap.		2003106	asbestos survey	Duct	intact	Throughout ceiling	July 2020

NMAH SPACE 3205C

										New Sample
ID	Status	Hazard Type	Description	Comments	Reference ID	Reference Source	Material Type	Material Condition	Material Location	Results
			Drywall/joint compound painted			28-Jul-20 OSHEM/Kapranos	Drywall and Joint	G = Good: material		
HAZ 20787	Removed	Asbestos	off-white and black.		2003106	asbestos survey	Compound	intact	Throughout room.	July 2020
						28-Jul-20 OSHEM/Kapranos		G = Good: material	Located at the HVAC	
HAZ 20789	Removed	Asbestos	Blue HVAC filter.		2003106	asbestos survey	HVAC Filter	intact	supply registers	July 2020
			Yellow HVAC duct insulation			28-Jul-20 OSHEM/Kapranos	Insulation, HVAC	G = Good: material		
HAZ 20788	Removed	Asbestos	with black painted wrap.		2003106	asbestos survey	Duct	intact	Throughout ceiling	July 2020