

TABLE 1

SUMMARY OF BULK SAMPLES COLLECTED
IN THE QUADRANGLE

Sample Number	Sample Location	Material Description	Asbestos Content
81905*	Room 1109	Lab Countertop	ND (None Detected)
81906	Room 1109	Lab Fume Hood	ND
81907	Mech. Rm. 3217MR	Brown Duct Mastic	ND
81908	Mech. Rm. 3217MR	Brown Duct Mastic	5-10% Chrysotile
81909	Mech. Rm. 3217MR	Yellow Duct Mastic	ND
81910	Hallway	White Duct Mastic	ND
81911	Hallway	White Duct Mastic	ND
81913	Loading Dock	Duct Insulation	ND
81914	Loading Dock	Duct Insulation	ND
81915A	Hallway to Loading Dock	Floor Tile	ND
81915B	Hallway to Loading Dock	Floor Tile Mastic	ND
81916	Hallway to Loading Dock	Fire Door Interior	ND
81917A	Room 1120	Floor Tile	ND
81917B	Room 1120	Floor Tile Mastic	ND
81918	Room 1120	Red Duct Mastic	ND
81919A	Room 1113	Sheet Vinyl Flooring	ND
81919B	Room 1113	Sheet Vinyl Mastic	ND
81920A	Hallway 2014	Floor Tile	1-2% Chrysotile
81920B	Hallway 2014	Floor Tile Mastic	ND
81921A	Hallway 2014	Floor Tile	1-2% Chrysotile
81921B	Hallway 2014	Floor Tile Mastic	ND
81923A*	Cold Storage Room	Sheet Vinyl Floor Strip	ND
81923B	Cold Storage Room	Sheet Vinyl Mastic	ND
81924	Mech. Rm. 3217MR	Grey Duct Mastic	ND
81925A	Inside Fan Housing	White Mastic	ND
81925B	Inside Fan Housing	Fibrous Insulation	ND
81922	Hallway 2014	Cove Mastic	ND

* QC Samples